



DE LOREAN MOTOR CARS OF AMERICA
Division of DeLorean Motor Company

SERVICE BULLETIN

NUMBER ST-08-10/82

Issued 10/18/82

CATEGORY: TECHNICAL

ATTN: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: BRAKE DISC RESURFACING
BULLETIN RENUMBERING

Please be advised that the service bulletin number for the above subject was incorrectly printed as ST-07-10/82.

THE CORRECT NUMBER SHOULD BE: ST-08-10/82

We regret this inconvenience.

In addition, after resurfacing any disc, the brake pads must be inspected to assure they have a flat and parallel contact surface. If this cannot be achieved, new brake pads should be installed.

Please correct your bulletin number and inform all personnel accordingly.

John J. Patro
Technical Publications Manager

JJP:slb