



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-20-10/81

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: OBSTRUCTION OF FOOTWELL VENTS

In the event of poor heater/air conditioning output from the footwell vents, check the following points:

1. Ensure that the driver's side footwell vent is not obstructed by either the tunnel carpet or the main wiring harness. Tuck or glue the carpet beneath the vent and route the harness securely over the vent outlet as necessary.
2. Ensure that the passenger's side footwell vent is not obstructed by the tunnel carpet. Tuck and glue the carpet down beneath the vent.

Please inform all personnel accordingly.

Lutz Feuerabendt
Technical Service Manager

LF:mc

Issued 10/26/81