


CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: WIRING HARNESS ROUTING ON RIGHT (REAR) BULKHEAD PANEL

From V.I.N. 2309, a recess has been cut out of the right rear bulkhead panel to accommodate the wiring harness. See the diagram below.

This modification may also be made on earlier vehicles to improve harness routing.



Please inform all personnel accordingly.

Lutz Feuerabendt
Technical Service Manager

LF:mc

Issued 10/26/81