



DE LOREAN MOTOR COMPANY

PARTS BULLETIN

NUMBER PS-01-9/81

CATEGORY: PARTS SUPERSESSION

ATTENTION: DEALER/PARTS MANAGER

SUBJECT: RADIO ANTENNA - FRONT HOOD

Windshield 100623

As of V.I.N. 2711, the windshield antenna has been excluded and an external radio antenna will be mounted on all cars.

The replacement windshield, part number 100623, has been superseded to part number 110076. When replacing a windshield on any car without an external antenna, a replacement antenna, part number A5000010, has to be fitted.

Part number 100623 is no longer available.

Please refer to Service Bulletin ST-12-9/81 of 9/2/81 for installation instruction.

Front Hood 109096

As of V.I.N. 3200, the front hood has been changed and the gas filler flap has been eliminated.

Replacement hood, part number 109096, has been superseded to part number 109134.

Part number 109096 is no longer available.

Sincerely,

Leif R. Montin
National Parts Manager

LRM:psg

ISSUED 9/22/81