



SERVICE BULLETIN

NUMBER SC-03-11/81

CATEGORY: SAFETY CAMPAIGN

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: SAFETY CAMPAIGN NO. RA-0001 (SERVICE BULLETIN SC-01-11/81)
RED PAINT MARKINGS - V.I.N. 2333 TO 5600

The factory has informed us that on vehicles from V.I.N. 2333 to 5600 a red paint marking on the ball joints and ball joint nuts has been used for other production identification reasons on vehicles affected by the above campaign.

Therefore, the red dot in the engine compartment and inspection of the ball joint nuts (must have castellated nuts and cotter pins) must be used to determine whether a vehicle has received the campaign work.

Please inform all personnel concerned.

Lutz Feuerabendt
Warranty Manager

LF:mc

ISSUED 11/20/81