



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-05-7/81

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: RADIO FACE PLATE DISTORTION

Reports have been received that the center upper and lower edges of the radio face plate may distort. This distortion may occur in very hot climates.

A repair solution is currently under development. We will inform you of this repair as soon as it becomes available.

Sincerely,

Lutz Feuerabendt
Technical Service Manager

ISSUED 7/9/81