



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-18-10/81


CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: VENT HOSE - CONTROL PRESSURE REGULATOR

The installation position of the vent hose on the control pressure regulator should be inspected and corrected on all DMC vehicles up to V.I.N. 2283, as well as on all DMC vehicles during service visits.

If necessary, to prevent kinking the vent hose should be rotated away from the air conditioning hose. (See Illustration)



Please inform all personnel accordingly.

Lutz Feuerabendt
Technical Service Manager

LF:mc

Issued 10/26/81