



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-21-10/81


CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: HOOD RELEASE

If the hood release fails to operate, the following is a method of release:

1. Remove the left front wheel.
2. Remove brake reservoir cover from below.
3. Using a hooked wire, reach through the aperture and release the hood latch. (See Illustration)



Please inform all personnel accordingly.

Lutz Feuerabendt
Technical Service Manager

LF:mc

Issued 10/26/81