



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-24-10/81

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: REVISED TORQUE SETTING

From V.I.N. 2474 the torque setting for upper and lower ball joint to steering knuckle has been revised to 70Nm (52 ft.-lb.).

Please update Service Bulletin ST-09-7/81 accordingly.

Lutz Feuerabendt
Technical Service Manager

LF:mc

Issued 10/26/81