



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-29-11/81

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: FREON CHARGE AIR CONDITIONING

The freon charge has changed to 2.2 lbs. from the previous 2.75 lbs..
The new specification was introduced with V.I.N. 4080.

If knocking noises are observed during starting with the air
conditioning on, the new freon charge specification should be used.

Please inform all personnel concerned.

Lutz Feuerabendt
Warranty Manager

LF:mc

Issued 11/24/81