



DE LOREAN MOTOR CARS OF AMERICA
Division of DeLorean Motor Company

PARTS BULLETIN

NUMBER PS-02-7/82

CATEGORY: PARTS SUPERSESSION

ATTENTION: PARTS MANAGER

SUBJECT: INERTIA SWITCH

INERTIA SWITCH 100815

As a result of Recall Campaign RA-0003 on Service Bulletin SC-06-7/82, the above inertia switch is now superseded by part number 111209. All outstanding backorders for the old part number are now cancelled. All unused stock of the old inertia switch 100815 should be returned to DMCA, Irvine, under parts return procedure.

Likewise, we cancelled your backorders for the inertia switch as replacement requirements will be done through the recall program. Should you require additional inertia switches other than recall program requirements, please reorder under part number 111209.

DE LOREAN MOTOR CARS OF AMERICA
PARTS DEPARTMENT

Rolando Balingit
National Parts Manager

RB/psg