



DE LOREAN MOTOR CARS OF AMERICA
Division of DeLorean Motor Company

SERVICE BULLETIN

NUMBER ST-10-10/82

Issued 10/18/82

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: ADDITIONAL LUBRICATION POINT -
SPEEDO ADAPTER

Please be advised that the speedometer 90° adapter (at left front wheel) has been added to the regular maintenance schedule for lubrication at each scheduled maintenance.

Procedure:

- 1) Remove speedometer cable from speedometer 90° adapter.
- 2) Rotate adapter 180° to bring the oil filler screw (originally pointing downward) so that it is pointing upward.
- 3) Remove oil filler screw and oil with SAE 80 or 90 gear oil. Reinstall filler screw.
- 4) Return adapter to its original position and connect speedometer cable.

Please inform all personnel accordingly.

John J. Patro
Technical Publications Manager

JJP:slb