



DE LOREAN MOTOR COMPANY

SERVICE BULLETIN

NUMBER ST-11-8/81

CATEGORY: TECHNICAL

ATTENTION: ALL DMC DEALERS/SERVICE MANAGERS

SUBJECT: BRAKE DISC - FRONT/REAR

For quality control reasons, front and rear brake discs should be replaced instead of machining and the defective disc(s) must be submitted together with the respective warranty claim(s).

This procedure is in effect until superseded.

Please inform all personnel concerned.

Sincerely,

Lutz Feuerabendt
Technical Service Manager

LF:dg

ISSUED 8/20/81